

Network Scanner Admin Tool change history

Version 03.02.0010

Corrected issue:

1. Two-byte-code characters are now available in a folder path to FTP.

Version 03.02.0008

New features:

1. The installer has been signed with a SHA256 digital signature.
2. The installer runs automatically when the setup file is downloaded.

Version 03.02.0007

New feature:

1. [IPv6](#) has been supported.
2. The installer has been signed with a SHA256 digital signature.

Version 03.01.0039

New feature:

1. Patch code files (for printing), which is for the separation function, are installed into the installation folder of the Admin Tool.

Version 03.01.0037

Added feature:

1. Windows® 10 is supported.

Corrected issues:

2. Fixed the following defects that may occur when connecting to N7100 through Admin Tool.
 - A. N7100 may not be able to connect with a PC through Admin Tool after changing a connection port or SSL settings.
 - B. A message of being used by an administrator may keep displaying for two minutes.
 - C. A communication error may appear when you disconnect through Admin Tool using https connection after setting a domain.
 - D. Displaying "Connecting..." message, login process from Admin Tool cannot proceed when a blank is included in your user name for Windows.
3. Fixed the defects that some items in Job Settings may not appear properly.

Version 03.01.0035

Corrected issues:

1. Fixed the problem where the security warning notifying "unknown publisher" is issued in some cases.
2. Fixed so that Job settings screen shall be displayed correctly.