

# fi-8190/fi-8290/fi-8170/fi-8270/fi-8150/fi-8250/fi-8150U/fi-8250U Firmware

## change history

### 0U00

#### Corrected issue:

1. Fixed the problem that occurs when multifeed is detected with a specific size of document, causing a delay in the multifeed error notification.

### 0T00

#### Corrected issue:

1. Fixed the failure of connecting imprinter for fi-81xx series.

### 0P00

#### Corrected issues:

1. Support for the Simplified Chinese fonts (GB18030-2022).
2. Corrects the problem in which a lamp circuit error (H7 error) is erroneously detected.

### 0L00

#### Corrected issues:

1. Fixed the problem that occurs when scanning in the emulation mode, causing an internal communication error which is indicated as the C8 error on the Function Number Display or an unexpected error on the LCD.
2. Fixed the problem of A1:B3 imprinter error.

### 0E00

#### New features:

1. IPv6 is now supported.  
(Target scanners: fi-8190, fi-8170, fi-8150, fi-8290, fi-8270, fi-8250)
2. PaperStream NX Manager is now supported.  
(Target scanners: fi-8190, fi-8170, fi-8150, fi-8290, fi-8270, fi-8250)

#### Corrected issue:

1. Fixed other minor problems.