

PaperStream IP (TWAIN) for SP Series change history

Version 3.54.0

New features:

1. The following new models are now supported.
SP-2240N/SP-2230N
2. The following features are supported on the SP-2240N/SP-2230N:
 - Carrier Sheet (Crop the whole document)
 - Hole Punch Removal
 - Edge Repair
 - Cropping (Document with Tab)
 - AIQC (fold/tear)

V3 Service Update 4

Version 3.42.1

Corrected issue:

1. Resolved an issue where the driver could not be launched when using PaperStream IP 3.42.0 in the following OS environments:
 - Windows Server 2016
 - Windows 10 Enterprise 2016 LTSC

Version 3.42.0

New features:

1. The following operating systems are now supported:
Windows Server® 2025 Standard

Improvement:

1. Fixed an issue where, when the background color was set to 'Black' and the deskew method was set to 'Correct document content skew', areas

that should have been filled in black were instead filled with the surrounding color.

2. Fixed an issue where a small black object appeared at the bottom-right corner of the output image when the image format was set to Tiff (G4) or Tiff (G32) in the driver.

V3 Service Update 3

Version 3.32.0

New features:

1. The following operating systems are no longer supported:
Windows Server® 2012 Standard, Windows Server® 2012 R2 Standard
2. Scanning profile exporter/importer supports selective export and additional import of profiles.

Improvement:

1. Fixed other minor problems.

V3 Service Update 2

Version 3.22.0

New features:

1. SP-30F is no longer supported.
2. The following operating systems are no longer supported:
Windows®7 Professional, Windows®7 Enterprise, Windows®8.1, Windows®8.1 Pro, Windows®8.1 Enterprise, Windows Server® 2008 Standard R2
3. The following 2D barcodes can be detected with the barcode detection function.
PDF417, QR Code, Data Matrix

V3 Service Update 1

Version 3.2.1

New features:

1. Added a function to automatically correct the orientation of the image based on the pre-registered information on the reference area for detecting the document orientation.
This enables the document orientation to be corrected for images whose orientation cannot be corrected even when [Automatic] is selected for [Rotation] in [Page].
Select the [Use custom rotation settings] check box to enable this function.
2. Added a function to automatically detect a passport when scanned on a flatbed.
This function is available with PaperStream Capture.

Improvement:

1. The scanner driver window has been renewed.
 - Added some setting items in the Simple dialog.
 - Improved the visibility and the accessibility of the setting items.

V2 Service Update 1

Version 2.14.2

Corrected issue:

1. Fixed the problem in which the following symptoms occur when the document is skewed by nearly 45 degrees during a scan.
 - Insufficient memory error is displayed
 - Image is output with large amount of blank spaces
 - Driver hangs

Version 2.14.1

Improvement:

1. Removed the limit on the number of allowable PaperStream IP installations from EULA so that a scanner can be shared.

Corrected issues:

1. Fixed the problem that occurs when Automatic Profile Selection is used in a general user environment, preventing specific document information from being added.
2. Fixed the problem in which opening and closing the cover is required for closing the error that occurs when a scanner failed to pick a paper to scan.
3. Fixed the problem that may occur in which, even when the style of a document is recognized to be identical to specific document information, the resolution specified in the normal dialog of PaperStream IP is applied for the document.
4. Fixed the problem in which Software Operation Panel does not occupy the connected scanner while allowing its device settings to be configured.

Improvement:

1. Removed the limit on the number of allowable PaperStream IP installations from EULA so that a scanner can be shared.

Corrected issues:

1. Fixed the problem that occurs when Automatic Profile Selection is used in a general user environment, preventing specific document information from being added.
2. Fixed the problem in which opening and closing the cover is required for closing the error that occurs when a scanner failed to pick a paper to scan.
3. Fixed the problem that may occur in which, even when the style of a document is recognized to be identical to specific document information, the resolution specified in the normal dialog of PaperStream IP is applied for the document.
4. Fixed the problem in which Software Operation Panel does not occupy the connected scanner while allowing its device settings to be configured.

Version 2.12.3

Corrected issue:

1. Fixed the problem that occurs when a scan is performed under the following conditions, causing abnormal end or hangup of the scanning application.
 - Driver: PaperStream IP for SP (TWAIN/TWAIN x64) 2.12.0
 - App: PaperStream Capture, or an app that shows no driver window during scan
 - User: No administrative privileges

Version 2.12.0

New features:

1. Windows Server® 2008 Standard has been removed from supported OS list.
2. Automatic Profile Selection has been added.
3. Through our unique image processing technology, it now outputs black and white images which are appropriate for OCR processing.
4. Software Operation Panel
 - Energy Star® 3.0 is now supported. The maximum period of time which the scanner automatically moves to power saving mode has been changed from 235 to 115 mins.

Service Update 8

Version 1.62.0

New feature:

1. Color Adjustment has been added.

Improvement:

1. Accuracy in automatic rotation has been improved in scanning business-card-size documents with background pattern in color under the setting where [Page] under [Rotation] is set to [Automatic].

Service Update 7

Version 1.52.0.6553

Improvement:

1. Low resolution images have less noise now.

Corrected issue:

1. Minor errors have been modified.

Version 1.46.0.5900

Corrected issue:

1. Minor errors have been modified.