

fi-8190/fi-8290/fi-8170/fi-8270/fi-8150/fi-8250/fi-8150U/fi-8250U Firmware

change history

0T00

Corrected issue:

1. Fixed the failure of connecting imprinter for fi-81xx series.

0P00

Corrected issues:

1. Support for the Simplified Chinese fonts (GB18030-2022).
2. Corrects the problem in which a lamp circuit error (H7 error) is erroneously detected.

0L00

Corrected issues:

1. Fixed the problem that occurs when scanning in the emulation mode, causing an internal communication error which is indicated as the C8 error on the Function Number Display or an unexpected error on the LCD.
2. Fixed the problem of A1:B3 imprinter error.

0E00

New features:

1. IPv6 is now supported.
(Target scanners: fi-8190, fi-8170, fi-8150, fi-8290, fi-8270, fi-8250)
2. PaperStream NX Manager is now supported.
(Target scanners: fi-8190, fi-8170, fi-8150, fi-8290, fi-8270, fi-8250)

Corrected issue:

1. Fixed other minor problems.