

Installation Instructions

1. Be sure you log into Windows® as a user with administrator privileges.
2. Download "WiniX500ScanSnapManualsV20LxxWW.exe" onto your hard drive.

Make sure you have enough free disk space (at least more than twice the download file size) for installing the programs.

3. Quit any applications that are running on your computer.
4. Execute the downloaded "WiniX500ScanSnapManualsV20LxxWW.exe" file to start the installation.
5. Follow the instructions from the Installation Wizard to complete the installation.
6. Check for [the latest software updates](#) and apply them before operating the scanner.